

Lipowerline F&Q

No.	Question Description	Solution
1.	Flashback occurs when opening software	Check the software installation directory. If the software is installed on C drive, select administrator status to run the software. If it is installed in other memory disk, please right click LiPowerline software - Properties - Compatibility - Windows7/Windows8 Compatible mode to run the software
2.	Software flashback problem after loading point cloud	 Check the software installation directory, such as installed in the C disk, select the administrator identity to run the software. check whether the memory disk where the point cloud is stored is full, please ensure a certain amount of memory space. Check whether the computer system graphics card driver is installed in the correct version,



	T	
		please use the system detection tool
		to install the most suitable graphics
		card driver.Check whether the point
		cloud has not been solved.
		1、LiPowerline will automatically read
		the last configuration when opened.
		2、If the working directory of the last
	"Failed to create cache directory" after loading data	configuration is renamed or deleted,
3.		read the document again according
		to the correct path.
		3 . If you need to open new data,
		please manually reset the working
		directory
		1, please do not move the data
		location or modify the data name
		during the software operation, such
4.	When moving data location or	as the need to modify the name of
	modifying data name, an error	the tower, in the cut file before
	occurs in software operation	editing the tower to complete, if you
		need to move the data location,
		when the software is not started, and
		pay attention to modify the working



		directory / output directory
		1) Please minimize the running of
		other programs when running
		LiPowerline, especially the programs
		with high memory and CPU/GPU
	Ground point	usage.
_	classification/slicing/hazard	2) It is recommended to separate the
5.	detection process is particularly slow	file cutting and classification, first cut
	or impossible	the file and then classify it, so as to
		reduce the amount of data to be
		classified, which can significantly
		shorten the time required for the
		classification process.
		1. Please check the xml configuration
		file, whether the safety distance of
		the feature is set according to the
	No hazard points after hazard point	requirements of the electrical safety
6.		regulations.
	detection	2 、 Please check whether the xml
		configuration file has been filled with
		relevant parameters according to the
		requirements for high vegetation,



		medium vegetation, low vegetation,
		buildings, up and down crossings,
		highways, railroads and other
		information.
		3. Please check whether the classified
		category contains accurate
		information of feature categories
		such as high vegetation, medium
		vegetation, low vegetation,
		buildings, up and down crossings,
		highways, railroads, etc.
		Please make sure the tower file -
7.	Unable to hang insulator operation	Type field selects the corresponding
		tower shape
		1 . Please check whether the
		classification ground wire
8.		2. Use insulator - insulator inspection
	Unable to generate conductors in	tool to check whether there is a
	bulk based on insulators	missing insulator or repeated
		insulator hanging situation.
		3、If you only need the whole section
		of the selected path within the



		individual sections of data for batch
		generation of simulated conductors,
		please check whether the data is in
		the complete range of
		tension-resistant sections.
		4 Please check whether the tower
		type filling content is correct.
		Please check whether the tower file
		serial number and point cloud
		naming correspond one by one.
		1. Please check the insulator hanging
		point position and adjust it to the
		right position.
9.	Misalignment problem with vector	2、Click Power Line - Fit power line
J.	power lines	based on insulator - Fit single power
		line, manually select insulator and
		power line hanging point to generate
		simulated wire.
10.	Insulator-based batch generation of wire and point cloud wire position deviation	1. Please check the insulator hanging
		point position and adjust it to the
		right position.
		2, please check the quality of data, if



		the wire category point cloud is
		sparse, or the lack of point cloud, will
		affect the automatic batch fitting
		wire effect, please click on the power
		line - based on insulator fitting
		power line - fitting a single power
		line, manually select the insulator as
		well as the power line Pendant point
		generation simulation wire
	Hazardous point detection, only red hazardous areas, no list of hazardous points.	Check whether the name of the cut
		file data and the name of the marked
11.		tower are consistent, the name of the
11.		cut file data is automatically
		generated by the software and
		cannot be modified manually.
		The installation directory
12.		LiPowerlineExe.exe may have been
	Software display please contact	deleted by the antivirus software,
	info@lidar360.com or	you need to exit the antivirus
	info@greenvalleyintl.com	software, or in 360 Security Guard,
		add the software installation
		directory to the trust area. Uninstall



		or delete the previous installation
		directory and reinstall LiPowerline
		software.
	Generate reports showing terminated tasks	The coordinate system in the project
		configuration is not selected, select
		the corresponding coordinate
13.		system again; if the category and the
		ClassNames.txt category in the cache
		folder are not the same, it will also
		lead to errors.
14.	Open the previously classified point cloud data, the classification color has changed	Tap the Reset button in the Tap Cloud menu page to open the data again.
15.	The software can not calculate the danger point, the detection distance set how much, can not detect the danger point	Computer file permissions, the shortcut properties in the compatibility check the "Run this program as administrator" can be solved.
16.	Failure to find small and large towers during danger point calculation	The number of marked towers and the number of cut file data names do not match.
17.	Open the dot cloud comes with pink.	Re-cut the file or use the clear



		function in Distribution Network
		Patrol.
		You need to move the previous
		authorization code out first, and then
18.	After activating the license code, the	activate the new one. If the
	software still won't open	computer's account is not in English,
		it is symbols and patterns will also
		not be authorized.
19.	Tower info is not enough.Cannot	Only one tower is marked, at least 2
	generate trajectory.	towers need to be marked